

# City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 7/15/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW


Manhole\_ID: S04AA\_009MH

Test ID: D1032-019008

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S04AA_009MH
0			Water Level	
96.09999847	10		Tap Factory	
96.09999847			Dye Test Visible	@ TBI - H(?) in lateral
96.09999847			Dye Test Visible	@ TBI - downspout
96.09999847	12		Tap Break-in	From 815 Winans Way
96.09999847			General Observation	NO CLEAN OUT FOUND OR TOILET ACC
96.09999847			Manhole	S04A_025MH
96.09999847			End of Survey	DYE TEST DONE